



- Installation**
1. Drill hole approximately 0.25" Deep
  - 1/4-28 Sensors: 6.8mm Drill Bit
  - M8x1.25 Sensors: 6.8mm Drill Bit
  2. Spot Face Sensor with Drill Bit
  3. Tap Hole for Required Thread Size
  4. Clean Debris from Surface
  5. Install Sensor
- Suggested Mounting Kit**
- CMC2270-D-1-T For M8x1.25 Sensors  
CMC2270-D-3-T For M8x1 Sensors

THIS DOCUMENT IS ISSUED AS AN INFORMATIONAL TOOL. IT IS NOT A CONTRACT. IT IS NOT A WARRANTY. IT IS NOT A GUARANTEE. IT IS NOT A COMMITMENT. IT IS NOT A PROMISE. IT IS NOT A CONTRACT. IT IS NOT A WARRANTY. IT IS NOT A GUARANTEE. IT IS NOT A COMMITMENT. IT IS NOT A PROMISE.

CUSTOMER		DRAWN		STI		STI Vibration Monitoring		REV	
LOCATION		N. Howard		N. Howard		League City, Texas		A	
ORDER NO.		N. Howard		N. Howard		N. Howard		A	
UNLESS OTHERWISE SPECIFIED		N. Howard		N. Howard		N. Howard		A	
ALL DIMENSIONS ARE IN INCHES.		N. Howard		N. Howard		N. Howard		A	
TOLERANCES:		N. Howard		N. Howard		N. Howard		A	
FRACTIONS: XX ± 0.01		N. Howard		N. Howard		N. Howard		A	
ANGLES: ± 1.0		N. Howard		N. Howard		N. Howard		A	
DECIMALS: .XXXX ± 0.0005		N. Howard		N. Howard		N. Howard		A	
DATE		N. Howard		N. Howard		N. Howard		A	

Notes:

- 1.
- 2.
- 3.
- 4.
- 5.